

REPORT NUMBER:

HGHT07608339





TEST REPORT

Number: HGHT07608339

Apr 20, 2023

Date:

Applicant: TONGXIANG FIRST LINE SILK VELVET CO.,LTD

NO. 80 FUYE ROAD FENGMING ECONOMIC

DEVELOPMENT ZONE, TONGXIANG

CITY, ZHEJIANG PROVINCE

Attn: CHLOE

Sample Description As Declared:

No. Of Sample : One (1)

Fibre Content : -

Material : Woven Fabric

Finishing : End Uses : Colour : White

Style No. : -

Order No./PO No. : FL-Teddy W00

Buyer's Name : -Manufacturer's Name : -Ref. : -

Applicant's Provided Care Instruction/Label: -

Date Sample Received : Apr 17, 2023 Date Testing Started : Apr 17, 2023

Prepared And Checked By:

For Intertek Testing Services Ltd., Hangzhou

Vivian Zhao Manager





TEST REPORT

Number: HGHT07608339

Tests Conducted (As Requested By The Applicant)

1 Total Fluorine (F) Content:

With Reference To EN 14582:2016 By Combustion In A Calorimetric Bomb And Determined By Ion Chromatography.

Compounds Result In ppm Requirement In ppm

(1)

Fluorine (F) Content ND -

Remark: Reporting limit = 20 ppm

ND = Not Detected

ppm = Parts per million = mg/kg

Test Component:

(1) White Color Face Thick Yarn Of Submitted Sample

End of Report

This report is made solely on the basis of your instructions and/or information and materials supplied by you. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or wilful misconduct.

This report shall not be reproduced except in full, without written approval of the laboratory.